SlimPRO Calibration Instructions

1. Press and hold **UNIT** button (on the bottom of the scale).

2. Install the batteries. All display segments will turn on.

3. Press **UNIT** button 4 times quickly and hold **UNIT** button on the fourth press until the scale shows the zero count.

4. Press **UNIT** button, and place the scale on the table or bench in 4 seconds.

5. The scale will show "0.0 kg" and then "65.0 kg".

6. Put 65kg of calibrated test weight on the scale.

7. The scale will show " 135.0 kg".

8. Put 135kg of calibrated test weight on the scale.

9. The scale will show "PASS", and then power off automatically.