


MRI/ CT/ X-Ray Testing Summary




- MRI Safe
- CT/ Xray
 Radiopaque

Oasis +



- MRI Safe
- CT/ Xray Radiopaque Strongest CT artifact

Azure




- MRI Safe
- Xray Radiopaque
- CT Radiolucent (thin gel top lining visible)

Oasis Elite



- MRI Safe
- CT/ Xray Radiopaque (PU expand foam),
- CT/ Xray Radiolucent (foams invisible- thin gel top lining visible)

ARDS/ Elite Foam



- MRI Safe
- CT/ Xray Radiolucent (Foam invisiblesimilar to air)

Radiolucent substances are materials that allow X-rays or other forms of radiation to pass through relatively easily.

Radiopaque substances are materials that do not easily allow X-rays or other forms of radiation to pass through and require higher radiation levels.